


- All dimensions are referred to base H
- △ Restricted area, no electrical parts, no components allowed
 - △ Hmax=0.4
 - △ Hmax=0.6
 - △ Hmax=0.75
 - △ Hmax=1.85
 - △ area for label
 - △ Hmax=1.4



Pin assignment	N0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
Symbol	GND	YU	XR	YD	XL	GND	NC	NC	NC	NC	NC	NC	NC	NC	VCC_3V0	GND	B0	B1	B2	B3	B4	B5	GND	G0	G1	VSYNC	HSYNC	NC	NC	LED-	LED+ GND
Symbol	G2	G3	G4	G5	GND	R0	R1	R2	R3	R4	R5	GND	PWR	LCD	NC	GND	LCD_CLK	GND	LCD_EN	SDO	NC	SDI	NC	SCL	VSYNC	HSYNC	NC	NC	LED-	LED+ GND	

All the dimensions with () or not marking positioning tolerance are reference.